
















## CARE LABELLING SYMBOLS - EN ISO 3758:2012

Symbols




UNI EN ISO 3758: 2012

Symbol	Washing process	
	— maximum washing temperature 95 °C — normal process	
	— maximum washing temperature 70 °C — normal process	
	— maximum washing temperature 60 °C — normal process	
	— maximum washing temperature 60 °C — mild process	
	— maximum washing temperature 50 °C — normal process	
1° POSITION 		— maximum washing temperature 50 °C — mild process
		— maximum washing temperature 40 °C — normal process
		— maximum washing temperature 40 °C — mild process
WASHING PROCESS		— maximum washing temperature 40 °C — very mild process
		— maximum washing temperature 30 °C — normal process
		— maximum washing temperature 30 °C — mild process
		— maximum washing temperature 30 °C — very mild process
		— wash by hand — maximum temperature 40 °C
		— do not wash

2° POSITION






BLEACHING  
PROCESS

Symbol	Bleaching process
	— any bleaching agent allowed
	— only oxygen/non-chlorine bleach allowed
	— do not bleach

3° POSITION











TUMBLE  
DRYING  
PROCESS


Symbol	Tumble drying process
	— tumble drying possible — normal temperature; exhaust temperature max. 80 °C
	— tumble drying possible — low temperature; exhaust temperature max. 60 °C
	— do not tumble dry

3° POSITION



NATURAL  
DRYING  
PROCESS


Symbol	Description	Symbol	Description
	— line drying		— line drying in the shade
	— drip line drying		— drip line drying in the shade
	— flat drying		— flat drying in the shade
	— drip flat drying		— drip flat drying in the shade



Symbol	Ironing process
	— iron at maximum sole-plate temperature of 200 °C
	— iron at maximum sole-plate temperature of 150 °C
	— iron at maximum sole-plate temperature of 110 °C without steam — steam ironing may cause irreversible damage
	— do not iron



Textile care process	
Symbol	Dry cleaning process
	— professional dry cleaning in tetrachloroethene and all solvents listed for the symbol F — normal process
	— professional dry cleaning in tetrachloroethene and all solvents listed for the symbol F — mild process
	— professional dry cleaning in hydrocarbons (distillation temperature between 150 °C and 210 °C, flash point between 38 °C and 70 °C) — normal process
	— professional dry cleaning in hydrocarbons (distillation temperature between 150 °C and 210 °C, flash point between 38 °C and 70 °C) — mild process
	— do not dry clean



Textile care process	
Symbol	Wet cleaning process
	— professional wet cleaning — normal process
	— professional wet cleaning — mild process
	— professional wet cleaning — very mild process
	— do not professional wet clean